

Service Service Service

HR7761
HR7762
HR7759



Philips Consumer Lifestyle

Service Manual

PRODUCT INFORMATION

- Product meets the requirements regarding interference suppression on radio and television.
- After the product has been repaired, it should function properly and has to meet the safety requirements as laid down officially established at this moment.

TECHNICAL INFORMATION

Voltage:	220-240V
Frequency:	50-60Hz
Speeds:	2+ pulse
Blender Jar capacity:	1.2L
Bowl capacity flour:	500g
Bowl capacity dry:	1.2L
Bowl capacity liquid:	2.1L
Mini chopper capacity:	250ml
Power cord length:	1m
Motor unit:	Variospeed
Safety:	Lid & bowl detection, Mechanical 1.5sec brake
Color:	White (HR7761, HR7762/0x) Black (HR7762/9x,HR7759/90)

DISASSEMBLY-AND RE-ASSEMBLE ADVISE

- No specific issues.












REPAIR INSTRUCTION

- No specific issues.





ACCESSORIES

- See exploded view for more information

EXPLODED VIEW & PARTLIST (ACCESSORIES)



EXPLODED VIEW & PARTLIST (MAIN UNIT)



HR7761/HR7762/HR7759

Partlist for Accessories

Pos	Service Code	Description	Remark
1	9965 100 51802	JAR LID STAR WHITE	
	9965 100 52991	JAR LID BLACK	FOR HR7762/90, HR7762/91
2	9965 100 51807	BLENDER JAR	
3	9965 100 51815	BLENDER CAP	
4	9965 100 51798	MINI CHOPPER STAR WHITE	
	9965 100 52997	MINI CHOPPER BLACK	FOR HR7762/90, HR7762/91
5	9965 100 59182	SEALING RING + BLENDER KNIFE	
6	9965 100 51804	PUSHER	
7	9965 100 60717	BOWL,BOWL LID&TOOL HOLDER	
	9965 100 60716	BOWL,BOWL LID&TOOL HOLDER BLACK	FOR HR7762/90, HR7762/91
9	9965 100 51806	SPATULA STAR WHITE	
	9965 100 52998	SPATULA BLACK	FOR HR7762/90, HR7762/91
	996510057539	SPATULA BLACK	FOR HR7759/90
11	9965 100 51816	KNEADING ACCESSORY	
12	9965 100 51808	BLADE UNIT	
13	9965 100 51796	EMULSIFYING DISC	
	996510057541	EMULSIFYING DISC	FOR HR7759/90
14	9965 100 51828	COARSE SLICING / SHREDDING DISC	FOR HR7762 ONLY
	996510057534	COARSE SLICING / SHREDDING DISC	FOR HR7759/90
15	9965 100 51826	FINE SLICING / SHREDDING DISC	FOR HR7762 ONLY
16	9965 100 51832	CHIP DISC (FRENCH FRY DISC)	FOR HR7762 ONLY
17	9965 100 51829	GRANULATING DISC	FOR HR7762 ONLY
18	9965 100 51831	ACCESSORY STORAGE TRAY	FOR HR7762 ONLY
19	9965 100 51825	PLASTIC INSERT HOLDER	FOR HR7761 ONLY
20	9965 100 51817	FINE SHREDDING INSERT DISC	FOR HR7761 ONLY
21	9965 100 51794	COARSE SHREDDING INSERT DISC	FOR HR7761 ONLY
22	9965 100 51819	GRANULATING INSERT DISC	FOR HR7761 ONLY
23	9965 100 51818	SLICING INSERT DISC 1.2MM	FOR HR7761 ONLY
24	9965 100 51812	SLICING INSERT DISC 2.4MM	FOR HR7761 ONLY

HR7761/HR7762/HR7759**Partlist for Main Unit**

Pos	Service Code	Description	Remark
25A	9965 100 51799	HOUSING ASSY OYSTER METALLIC	
25B	9965 100 51827	HOUSING ASSY BLACK	FOR HR7762/90, HR7762/91
26A	9965 100 51809	BOTTOM ASSY OYSTER METALLIC	
26B	9965 100 51833	BOTTOM ASSY BLACK	FOR HR7762/90, HR7762/91
27	9965 100 51814	SUCKER FOOT (1PC)	
28	9965 100 51821	MOTOR INCL. WIRES + GEAR BOX (220-240V)	
29	9965 100 51795	MICRO SWITCH + SWITCH HOLDER	
30	9965 100 51805	SWITCH ASSY	
31	9965 100 51822	CORD STORAGE	
32A	9965 100 51797	CORDSET WEU WHITE	FOR EUROPE
	9965 100 52994	CORDSET WEU BLACK	FOR HR7762/90, HR7762/91
32B	9965 100 51803	CORDSET AU WHITE	FOR AUSTRALIA
	9965 100 52992	CORDSET AU BLACK	FOR HR7762/90, HR7762/91
32C	9965 100 51801	CORDSET UK WHITE	FOR UK
	9965 100 52995	CORDSET UK BLACK	FOR HR7762/90, HR7762/91
32D	9965 100 51801	CORDSET SG WHITE (SAME AS UK)	FOR SINGAPORE
	9965 100 52995	CORDSET SG BLACK (SAME AS UK)	FOR HR7762/90, HR7762/91
32E	9965 100 51803	CORDSET SWITZERLAND WHITE (SAME AS AU)	FOR SWITZERLAND
	9965 100 52992	CORDSET SWITZERLAND BLACK (SAME AS AU)	FOR HR7762/90, HR7762/91
33	996510070629	SWICH KNOB RING,W/S	FOR HR7759/90

Revision list

1. Version 1.3, making parts 7,8 and 10 as one spare part(pos 7) for the matching issue.
2. Version 1.4, correct supplier's wrong factory code issue for position 5, so the service code for position 5 changed.
3. Version 1.5, Spray paint handle cover & lid cap changed from spray paint to in-mould color, so the position 7 service code changed.
4. Version 1.6, modify the bowl capacity.
5. Version 1.7, add new model version HR7759/90---WK1422