



Service information

Reference no.: GDA_108556

Symptom

Water container float

Cure

INFO:

For all Senseo models, excluding Senseo2, the float is now available as a spare part. When a water container is presented with a rusty magnet in the float, it can be easily replaced. please note that when replacing the float also the metal spring holding the float in place needs to be replaced, as it cannot be reused.

- 422224006491 Float spring
- 422225948814 Float assy

REMARKS:

- 12-11-2014: Initial version