



**Service information**

**Reference no.: GDA\_111873**

**Symptom**

Assembly code not available for "Pin for flow selector faucet" in XSmall Puro HD8642 and HD8643.


**Cure**

**INFO:**

The assembly code 421944022901(PIN FOR FLOW SELECTOR FAUCET XS4 ASSY) is no longer available. Only the single parts can be ordered.

**CURE:**

Order the below parts individually:



- 02 - 170320702 996530019707 O RING 100 SILICONE
- 03 - 9011.132 996530048874 SS SPRING FOR PIN
- 04 - 12000450 996530007819 SCREW TCBR TORX 10 3,5X12 PLAST.ZN-N
- 05 - 11009019 996530005183 TEA/BRASS PISTON L=20,9 ASSY.
- 06 - 11005099 996530002747 NATURAL CURSOR V2 FOR BOILER P119
- 07 - 421944022881 PIN FOR FLOW SELECTOR FAUCET XS4
- 08 - NM01.035 996530059399 OR ORM 0090-20 SILICONE
- 09 - NM01.057 996530059419 OR ORM 0050-20 IN SILICONE

**ADDITIONAL INFORMATION:**

**SERIAL NUMBER (First serial where solution has been implemented in production):**

None.

**IPM NUMBER (Philips Integrate Problem Management documentation reference number):**

None.

**FAQ NUMBER (for Call Center reference):**

None.

**INFORMATION FOR CALL CENTER:**

None.

**INFORMATION FOR CONSUMER:**

None.

**HISTORY:**

20/10/2015 - First Release