



Service information

Reference no.: SDA_101539

Symptom

Two different types of boiler for Poemia machine

Cure

INFO:
Poemia (Type HD8323-HD8325-HD8327) equip with a different type of boiler.

CURE:
Some version of Poemia (Type HD8323-HD8325-HD8327) are equipped with a different type of boiler : aluminum boiler instead stainless steel boiler.

Pay attention to used the correct exploded views in AYS on appliance repair:
Exploded view E74168 for machine with stainless steel boiler (Image 1). In Image 2 you can see the Stainless Steel Boiler.
Exploded view E71095 for machine with aluminum boiler (Image 3). In Image 4 you can see the Aluminum Boiler.

Image 1- E74168 for Stainless Steel Boiler




Image 2 -Stainless Steel Boiler



Image 3- E71095 for Aluminum Boiler




Image 4 -Aluminum Boiler

