



Service information

Reference no.: SDA_102061

Symptom

Cpu replacement in XSmall V2 with slim boiler from S/N 9010SR40003321.

Cure

INFO:

Cpu replacement in XSmall V2 with slim boiler from S/N 9010SR40003321 and Erratum sheet.

CURE:

In case of replacement of the CPU board cod.11022509 (996530007392) provide a **color printed copy** of the new descaling procedure (attached) to the Consumer.

HISTORY:

21/10/2013 - First Release