



Service information

Reference no.: SDA_104679

Symptom

Oil present in the machine and Bean Error.

Cure

INFO:

Machine shows the Bean Alarm, it is not possible to reset the alarm. Enough beans are present in the bean container. During inspection oil leakage from the piston unit assy is observed. A leak in the hydraulic system can be detected by attempting to move the piston by hand when the machine is not in use. When the piston moves by hand more than 5mm, there is a leak in the piston unit assy.

CURE:

Replace the piston unit assy with a new one, code 421941279572. The oil is vegetable and thereby food-approved. Clean any oil residue with a dry cloth.

HISTORY:

04-04-2014: Initial version