



Service information

Reference no.: SDA_104928

Symptom

Components of Cordwinder not available anymore

Cure

SYMPTOM:
The single components of Cordwinder assies are not available.

INFO:
Suppliers cannot deliver anymore the single components of Cordwinder assies.

CURE:
In case of complaints and/or defect components : the complete
Cordwinder assy should be replaced.

REMARK:
This is valid for **ALL** Bag-appliances and Bagless-appliances !!