Reference no.: SDA_106842



Service information

Symptom

 $combine\ BOWL, HANDLE\ and\ INTERLOCK\ ROD\ as\ one\ spare\ part\ for\ HR7776/RI7776, HR7777, HR77778/RI7778\ and\ HR7782/RI7782$

Cure

we combine bowl, handle and interlock rod as one spare part. Below are the details:

For the Avance food processor HR7776/RI7776,HR7777,HR77778/RI7778, the old spare part 12NC as below

Pos	Old 12NC	Description
27	996 5100 69733	BOWL
31	9965 100 56741	BOWL HANDLE
32	9965 100 56773	BOWL SAFETY LEVER

the new one is

Pos New 12NC Description 27 996510070034 BOWL ASSY

For the Remy food processor HR7782/RI7782, the old three spare part 12NC as below

Pos	New 12NC	Description
25	9965 100 57563	BOWL
26	9965 100 57573	HANDLE
27	9965 100 57581	INTERLOCK ROD
Al	12NC:-	

the new spare part 12NC is

 Pos
 New 12NC
 Description

 25
 9965 100 70035
 BOWL ASSY

Attention

Because this change was not quality improvement, please use the old stocks up. But the old parts and the new one are not interchangable. The new old can replace the old ones. If repair center order one of the old three parts, they must make sure that they have the other two old spare parts, or they must order the three old parts together.