



**Service information**

**Reference no.: SDA\_106875**

**Symptom**

attention on Avance food processor current PCBA for HR7776,HR7777,HR7778,RI7778/00,RI7776/90

**Cure**

For these models: HR7776 HR7777 HR7778 RI7778/00(886777800240) RI7776/90(886777690240 ), here comes an important clarification, please note.

1. The current spare part—PCBA (996510069354) can be only used on the products which produced before wk1413, except for below four POs & PCBA Date Code. All below spare parts should be on hold until further notice.

Philips PO PCBA Date Code  
APC-SGP069567 S140320  
APC-BRA069824 S140325  
APC-BRA070662 S140502  
APC-SGP071028 S140418

2. We have created two new spare part 12NC: PCBA (996510071054) for HR7776 HR7777 HR7778, and PCBA (996510071065) for RI7778/00(886777800240) RI7776/90(886777690240 ). They have no date code limitation, you can use this spare part in any date code units for repairing.