



Service information

Reference no.: SDA_112633

Symptom

attention on Food Processor BOWL for HR7774 HR7775 RI7774 RI7775

Cure

For the model: HR7774/RI7774 HR7775/RI7775 here comes an important clarification, please note.

Due to no initial SBOM in SPA2 system, we have done a manual change for the part ---420303582570 which has been replaced by 996510075063 and is used on below models:

HR7774/90
HR7775/00
RI7774/90
RI7775/00

If there is any demand for this BOWL, please do remember to order the new code--996510075063.