



Service information

Reference no.: SDA_81200

Symptom

Obstruction of brewing unit in Incanto and Royal

Cure

INFO:

Obstruction of brewing unit filter in Incanto series till the serial number 9009SA40073438 and Royal series till the serial number 9009ROY0738293.

CURE:

Replace the original filter (image 1) with the modified filter (image 2) using the kit number 20000400.

