

Reference no.: SDA_85196



Service information

Symptom

My coffee is not strong or mild enough in the max coffee setting.

Cure

INFO: My coffee is not strong or mild enough in the max coffee setting. How to set the motor grinder in a stronger or milder coffee position?

CURE: When in the maximum setting, the coffee is not strong or mild enough; the motor grinder can be changed in a stronger coffee position by turning the gearwheel 4 a couple of gear teeth to the left. The motor grinder can be changed in a milder coffee position by turning the gearwheel 4 a couple of gear teeth to the right.

