

Service information

Symptom

Reference no.: SDA_85757

Lots of steam and gurgling but no coffee

Cure

INFO: We have observed in the field that the water circuit of the appliance can become clogged or obstructed either by coffee beans accidentally dropped in the reservoir or by a defective or calcified checkvalve in one of the hoses to the heating element.

CURE: Make sure there are no beans obstructing the water flow from the reservoir to the heating element. Also check the operation of the checkvalve, when it is heavily calcified or defective, replace it (4222 459 53231).