



**Service information**

**Reference no.: SDA\_86737**

**Symptom**

Leakage from safety valve's plastic pipe fitting connection

**Cure**

**INFO:**

Leakage from safety valve's pipe fitting connection in Royal, Spidem My Coffee, Xsmall, Syntia, Gaggia Brera, Gaggia Platinium and Unica, Odea, Incanto, Cafè Crema and Espresso Italiano.

**CURE:**

Replace the original safety valve, that has a plastic pipe fitting connection, by the safety valve with brass pipe fitting, part code 11004689.