

Reference no.: SDA_90429

Service information

Symptom

Coffee powder under the brewing group

Cure

INFO: Self learning of "Saeco Adapting System" Software about dose quantity in Intelia Line.

CURE:
The customer can find residues of ground coffee under the brewing group, this is due by the Self Learning dose that will fit in the first period of use of the machine.