



Service information

Reference no.: SDA_90604

Symptom

Incanto line (Eng)

Cure

INFO:

01. Type of machine: Incanto Line
Content: **Situation „water tank empty“ and „no water“**
02. Type of machine: Incanto Line without display
Content: **Hide modes**
03. Type of machine: Incanto Sirius
Content: **New software 2.00.1**
04. Type of machine: Incanto de Luxe
Content: **Aqua Prima implemented ad**
05. Type of machine: Incanto line
Content: **Connectors CPU**
06. Type of machine: Incanto Line
Content: **Kit hinge door 226481426 silver – 226481450 black**
07. Type of machine: Incanto Linie
Content: **Micro switch hot water / steam valve**
08. Type of machine: Incanto de luxe, Rondò, Classic, Sirius
Content: **„no beans“ ad**
09. Type of machine: Grinder Incanto S-Class
Content: **Sensor grinder**
10. Type of machine: Incanto Linie
Content: **New hot water /steam valve leaky**
11. Type of machine: Incanto de Luxe
Content: **Defiate red silico tube**
12. Type of machine: Incanto Line
Content: **Reed sensor water tank**

CURE:

Please see the attached file in Eng.