



Service information

Reference no.: SDA_90842

Symptom

Other matters in all automatic machines.

Cure

INFO:

01. Type of machine: no type
Content: **automatically cleaning program with tab**
02. Type of machine: spares
Content: **20003254 Kit brewing valve – for Aluminium heater**
03. Type of machine: all
Content: **check the correct steam and temperature to get good milk foam**
04. Type of machine: all with diagnose mode
Content: **Display ad „water circuit priming“ in display machines**
05. Type of machine: all
Content: **pump sucks no water**
06. Type of machine: All with old grinder
Content: **Coarse coffee powder – grinder not fixed**
- 06a. Type of machine: Magic Comfort / Magic Comfort +
Content: **Connector JP22 is responsible to switch to different displays.**
07. Type of machine: Incanto de luxe, Rondò, Classic, Sirius
Content: **Grinder motor**
08. Type of machine: all
Content: **Install tool for the brewing group**
09. Type of machine: Alle
Content: **Calculation water hardness**
10. Type of machine: Cermic Grinder
Content: **Slow coffee dispense**
11. Type of machine: SPIDEM – My Coffee / My Coffee RS (Rapid Steam)
Content: **CPU 11008599 – JP3**
12. Type of machine: Alle
Content: **Noise from the gear motor**
13. Type of machine: Decalcifier
Content: **Damage of plastic**
14. Type of machine: Milk Island
Content: **Modifications**
15. Type of machine: Alle
Content: **New serial numbers**

CURE:

Plese see atatched the file in Eng.