



Service information

Reference no.: SDA_98593

Symptom

New descaling process in Syntia family and Gaggia Brera

Cure

INFO:
Improve the process of descaling..

CURE:
Starting for these new software:

- SYNTIA CLASS 230V:
- SW V.05.19.09 for machine up to S/N TU901215060935 with Old Standard Boiler
 - SW V.06.19.09 for machine from S/N TU901215060936 with Slim Boiler

SYNTIA CLASS 120V:
SW V.06.19.06

SYNTIA FOCUS and GAGGIA BRERA 230V:
SW V. 06.19.09

SYNTIA FOCUS and GAGGIA BRERA 120V:
SW V.06.19.06

SYNTIA CAPPUCCINO 230V:
SW V.06.13.05

SYNTIA CAPPUCCINO 120V:
SW V.06.02.03

The new descaling process has been implemented : now the descale solution clean also the brew unit.
Uploaded always the new software available in SSC.
Attached the new descaling procedures instruction for Syntia Class, Focus and Gaggia Brera; a copy has to be provided to the Consumer after this uploading.
In Syntia Cappuccino the instruction for the descale procedure doesn't change because there aren't necessary new interaction with the user.

Note:
When the machine is reprogrammed with new software, a descaling cycle must be done. The new software is going to reset all values and counters on the main board.

HISTORY:
18/07/2013 - Second review - Includes SDAs_95350 - 90557 - 90856 - 95337-98752 - 98728
29/05/2013 - First Release