



Service information

Reference no.: SDA_98757

Symptom

Software Update History for Intuita

Cure

INFO:

INTUITA 230 VOLT:

- V. 00.02.06
- ? Added the Powder Killer system implementation: now the coffee is poured into the dreg drawer only after wet.
- ? The second phase of descaling uses cold water
- ? Change "LED rinsing" against "LED ready to use"
- ? EEPROM version manager and automatic update of "water hardness" parameter when changing EEPROM version from V.0 to V1
- ? Updated the Serconf configuration

- V. 00.01.00
- ? avoid the thermostat fuse break.
- ? Update descale : better count of descale impulses for steam.

- V.00.00.19 First Release

INTUITA 120 VOLT:

- V.05.02.03 First release

CURE:

Update always the new software available in SSC.

HISTORY:

- 27/03/2013 - Added link to the sda_97067
- 29/10/2013 - First review - Includes SDA 97067
- 10/06/2013 - First Release