



Service information

Reference no.: GDA_109332

Symptom

Xsmall POL 2014 HD874331 no exploded view available

Cure

INFO:

The XSmall HD8743/31 is not inserted in exploded view E74159.

CURE:

The following details vary and are not yet present in the exploded E74159, refer to the below codes for spare part ordering. The exploded view will be update with the next release

Pos.35 page 1a/7 **cod. 421941215401 Cod. 11022509 CPU+SW P0057 XSMALL V4 230V ASSY.**

Pos.39 page 1b/7 **cod. 421944035511 DISPL.BOX XSMALL METRO**

Pos.01 page 2/7 **cod. 421944033061 SIL CONTR.KNOB COVER S/SCR.P0057**

ADDITIONAL INFORMATION:

Exploded View E74159 Attached.

SERIAL NUMBER (First serial where solution has been implemented in production):

None.

IPM NUMBER (Philips Integrate Problem Management documentation reference number):

106976.

FAQ NUMBER (for Call Center reference):

None.

INFORMATION FOR CALL CENTER:

None.

INFORMATION FOR CONSUMER:

None

HISTORY:

09/02/2015 - First Release