

Reference no.: GDA_111829



Service information

Symptom

GC96xx After service repair letter

Please refer to attachments for the "after service repair letter" which is aimed to guide consumers on the water advise and the decalc steps.