

Service information**Reference no.: GDA_97843****Symptom**

Seal on dirty watertank lid is damaged

Cure**SYMPTOM**

Seal on dirty watertank lid is damaged

INFO

2 tapes are added to assure that seal will stay at his place, see picture



Per wk. 1314 the tapes are added during assembly of the appliances

REMARK

Tapes can be removed easily by customers