



**Service information**

**Reference no.: SDA\_101740**

**Symptom**

DAMAGE OF KEYBOARD ON GRAN BARISTO REPAIR

**Cure**

**INFO:**  
How to prevent damage of capacitive keyboard flat cables during the repair.

**CURE:**  
Every time that it's necessary to access inside the machine, after removing of the two lateral panels, the capacitive keyboard must be fixed on the appliance sides with paper adhesive tape, as shown in the image 1.

**NOTE:** Take care to not cover keyboard with the tape (see in Image 2).

Image 1



Image 2



Now it's possible to remove the top cover and make the necessary repair.  
Remove the tape only after re-assembly of top cover, before re-insert two side panels.