



**Service information**

**Reference no.: SDA\_106453**

**Symptom**

Some ground coffee can block the coffee funnel (Conveyor) inside the machine.

**Cure**

**INFO:**

Work instructions for the coffee funnel (Conveyor) cleaning have been created and added to prevent the coffee funnel from getting clogged. Consumers need to clean it weekly.

**CURE:**

Add the work instructions to all repairs done on the Minuto, up to SN TW901406092405 before sending back the machine to the consumers.

**SERIAL NUMBER:**

Up to TW901406092405

**IPM NUMBER:**

39258

**FAQ NUMBER:**

See also FAQ E38\_MINUTO1\_CLEAN\_99487 on "How do I clean my Minuto?"

**INFORMATION FOR SERVICE CENTER:**

Add the work instructions when the machine is sent back.

**INFORMATION FOR CONSUMER:**

YES

**REMARK:**

25/07/2014 - Upload information

18/07/2014 - First Release