



**Service information**

**Reference no.: SDA\_111842**

**Symptom**

Dust comes out exhaust filter and Dust inside the appliance

**Cure**

**SYMPTOM:**

All FC616x appliances and FC6170 appliance show during usage that dust is coming out via exhaust area's  
and all the appliances show dust inside te appliance

**CURE:**

Use a new, better, filter which avoids this problem.  
Code of the new filter : 4322 004 94361

**REMARK:**

Every appliance which comes back for repair, independent on the kind of claim,  
**ALWAYS** the filter needs to be replaced with this new filter 4322 004 94361.

**INFO:**

Enclosed the specification of this new filter.