



Service information

Reference no.: SDA_78862

Symptom

When the lid is fitted to beaker, plastic powder is come out due to the edge of beaker is sharp and narrow groove of the lid.

Cure

The parting line at the beaker opening was moved from side to top, so there is no edge to scratch the lid (material: LDPE)