

## Service information

Reference no.: SDA\_79280

## **Symptom**

Spring change on shaving unit

## Cure

INFO

we have only on service shaving units without spring.

CURE:

1\*take the shaving unit from the shaver.

2\*bring the spring in the position so it is in the closed position at the shaver.

3\*push the yellow part to the above side of the spring

4\*take the spring out of the unit

5\*place the spring in the new unit

6\*bring the spring in the shaver cloced position

7\*place the yellow part in the correct position

8\*new shaving unit is complete