



Service information

Reference no.: SDA_80631

Symptom

Obstruction of brewing unit in Talea and Odea lines

Cure

INFO:
Obstruction of brewing unit in Talea and Odea line till the serial number 9008SA40343568.

CURE:
Replace the Beltrami filter (part number: 11009161, picture 1) with the Elfo filter, part number: 996530050709 (9161.268) (picture 2). The brewing unit modified is indicated in production with a white spot until January 2009 (picture 3).

Picture 1



Picture 2



Picture 3



HISTORY:
23/07/2013 - Second review
05/07/2010 - First Release