



Service information

Reference no.: SDA_85580


Symptom

Replacement water container assy is missing lid

Cure

INFO:

It has been decided to skip the water container cover for all Senseo II Water Container assies from production week 1110 onwards.



CURE:

Replace any defective or malfunctioning water container with the supplied one, if possible or preferred, transfer the cover from the original Water Container.