



**Service information**


**Reference no.:** SDA\_86551

**Symptom**

HD7740 Grind & Brew - Hinge cover in service part 4222 459 48321 doesn't fit

**Cure**

INFO:



older housing, also a hinge cover and a sachet with two screws is supplied. Due to a mix up at the supplier a wrong model hinge cover might have been supplied. It was not possible to trace back the timeframe during which the wrong part had been supplied.



CURE:

Exchange the Filter holder housing as you would normally do, but use the original hinge cover to reassemble the appliance.