



Service information

Reference no.: SDA_90560

Symptom

SBS brew unit

Cure

INFO:

When the machine delivers a coffee product, the brewing group begins to emit a whistle sound at Xelsis and Exprelia line.

CURE:

Remove the top of the valve, by turning and take it out (Image 1).

Remove the spring indicated (Image 2).

Eliminate the end of the spring (the last part),(Image 3).

Replace the spring with the cut side up to avoid damaging the gasket. (Image 4)

