



Service information

Reference no.: SDA_90734

Symptom

Water/coffee underneath the machine - cleaning after repair.(Eng-Deu)

Cure

INFO:

01 Eng. Typ of machines: all

content: **water/coffee underneath the machine - cleaning after repair**

01 Deu. Gerätetyp: Alle

Inhalt: **Reinigung nach der Reparatur**

CURE:

Please see attached the file in Eng. and Deu.