



Service information

Reference no.: SDA_94385

Symptom

Problems fitting nozzle/stick together

Cure

INFO:

When the nozzle of the AquaTrio FC7070 appliance needs to be refitted on the stick, it has been found that sometimes the electrical connections are hard to fit.

CURE:

Use a small screwdriver or small pliers to recenter the electrical pins in the connector before attempting to refit the nozzle to the stick. this will help installing the nozzle back.

REMARKS:

07-08-2012: Initial version