



Service information

Reference no.: SDA_98287

Symptom

Black milk-air flow selector of multivalve broken, new component available.

Cure

INFO:
Black milk-air flow selector of multivalve broken.

CURE:
If the black milk- air flow selector is broken, exchange with a new one, code 996530006868 (see Image 1).

Image 1

